

To Ingrid Hopkins/R3/USEPA/US@EPA

CC

bcc

Subject Benning Generating Station NPDES Permit Metals Letter

Dear Ms. Hopkins, Please find attached, a letter of explanation concerning the metals excursions at the Benning Generating Station. You will also receive a copy of this letter by certified mail.

If you have any questions, please contact me.

Regards,

Shirley Harmon

Shirley H. Harmon
Power Plant Asset Manager
Pepco Energy Services, Inc.
office/ 703-253-1787
fax/ 703-253-1799
mobile/ 202-841-1344
sharmon@pepcoenergy.com

Shirley H. Harmon Power Plant Asset Manager Pepco Energy Services, Inc. office/ 703-253-1787 fax/ 703-253-1799 mobile/ 202-841-1344



sharmon@pepcoenergy.com PES letter to EPA Hopkins NPDES metals excursion 4-16-2010.pdf



Sent via Electronic Mail and Certified Mail 7003 3110 0000 9187 9311

Return Receipt Requested

April 16, 2010

Ms. Ingrid H. Hopkins Water Protection Division (3WP42) U.S. EPA - Region III 1650 Arch Street Philadelphia, PA 19103-3029 (215) 814-5437 hopkins.ingrid@epa.gov

Re: Benning Generating Station - NPDES Permit No. DC0000094

Metal excursion at outfall 013

Dear Ms. Hopkins:

This letter follows up on the April 13, 2010 telephone notification, made on behalf of Pepco Energy Services, Inc. by Mr. Bruce Krepley, acting EHS Manager to report copper, iron, and zinc excursions in a grab sample collected from outfall 013 on March 12, 2010. The NPDES Permit requires a quarterly storm water sample to be collected at this outfall. The facility became aware of the daily maximum excursions upon reviewing the laboratory report on the afternoon of April 12, 2010. Mr. Bruce Krepley made a telephone notification to the U.S.E.P.A. on April 13, 2010 within the 24-hour notification period as required by permit NPDES DC0000094, condition VI.6.

The results are as follows.

Metal	Units	Permit Limit Daily Max.	Results Daily Max.
Copper	mg/L	0.0134	0.055
Iron	mg/L	1	5.7
Zinc	mg/L	0.117	0.53

The incident is under investigation. A definitive explanation has not yet been established however, it is believed that the snowmelt from the record February snow storms (over 32 inches of snow for the month) accompanied by the sand, salt and dirt from plowing and sanding activities at the facility was a contributing factor to the excursions at outfall 013. The majority of storm water from the entire facility flows to outfall 013. Pepco Energy Services, Inc. will continue its investigation for the source of these metals and will take

1300 North 17th Street • Suite 1600 • Arlington • VA • 22209 • 703-253-180 • Fax 703-253-1799 • www.pepcoenergy.com

Pepco Energy Services, Inc. is not the same company as Potomac Electric Power Company (Pepco), the regulated utility, and prices and services of Pepco Energy Services, Inc. are not set by the Public Service Commission.